


# Schematic Diagrams




AC100-120V

|    | AC CORD LIST  |
|----|---------------|
| US | 1AV4W11B20500 |

## CAUTION

Fuse of the specified parts number must be used. Unauthorized substitutions may result in fire or accident.

⚠ LP901  
METAL HALIDE LAMP  
150W  
1AV4T30B10000



**HOT!**

**COLD**

